Work Order ID 57838 Friday, April 16, 2010 12:57:33 PM								•					Page 1
Item ID: Revision ID:	D3911-7			· A	Accept					Setup	Start		
Item Name:	Basket Plate-Ey	ebolt Receiver		•							Stop		
Start Date: Required Date: Reference:	4/19/2010 4/23/2010	Start Qty: 24.00 Req'd Qty: 24.00		1881 1891 1891 1881 1881 1891 1891 1881		Cust Iter							
Approvals:		: MK		10-4-1b	Tooling: SPC (Y/N):		Date:			Run	Start Stop		
Sequence ID/ Work Center II		Operation Description			Set Up/ Run Hours	Draw Numbe	Draw r Rev.	Plan Code	Accep Qty	t Re Qt	•	Reject Number	Insp. Stamp
Draw Nbr	Revi	sion Nbr									··· / "		
D3911	С												
100 Waterjet		Мето		١	0.00			ı	R	10-4	- 19		
FLOW CNC Waterj		Cut as per D DWG REV: PROG REV DEBURR	2	-	r Mi	h wh	94/14	(2)	7)			(3	
110 QC Quality Control		QC2- Inspect parts off m Memo	*		0.00	,			也	ان-د	1-19		

Dart Ae	rospace	: Ltd							£ .
W/O:			W	ORK ORDER CHANGES	}	· · · · · · · · · · · · · · · · · · ·	 		
DATE	STEP	PRO	PROCEDURE CHANGE			Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No):	PAR #:	Fault Cat	egory:	NCR: Yes	No DOA:		Date:	
		esolution:							
NCR:		,	WORK ORE	DER NON-CONFORMAN	CE (NCR)			
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Section E Action Description Chief Eng	Sign & Date	Verificat Section	1	Approval Chief Eng	Approval QC Inspector
	1		1		1	4	J	I	i

NCR:		V	VORK ORD	PER NON-CONFORMANC	E (NCR)			
		Description of NC	cription of NC Corrective Action Section B					Ammunial
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Approval Chief Eng	Approval QC inspector
								-
	ŀ							
								-

Work Order ID 57838

Friday, April 16, 2010 12:57:33 PM



Page 2

Item ID:

D3911-7

Accept

Setup Start

Stop



Revision ID:

Item Name:

Basket Plate-Eyebolt Receiver

Start Date: 4/19/2010

Required Date: 4/23/2010

Start Qty: 24.00

Req'd Qty: 24.00



Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan:

Date: _____ Date: _____ SPC (Y/N):

Tooling:

Date:

Date:

Run

Start

Stop



Set Up/ **Run Hours**

Draw Number

Plan Draw Rev. Code

Accept Qty

Reject Qty

Reject Number Stamp

Insp.

Sequence ID/ **Work Center ID**

120

Quality Control

Operation Description

QC8- Inspect parts - second check

Memo

Identify as per dwg & Stock Location:

0.00

130

Packaging Packaging

Memo

0.00

0.00

ú.

140

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

10/04/22 A MF 10-4-22

Dart Aerospac	ce Ltd
---------------	--------

w/o:5	7838	WORK ORDER C	HANGES				
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
olula	出几	Took Of to For Occ inspection template	5	10/04/20	*(Soloules

Part No: <u>→3911-7</u>	PAR #: Fa	nult Category:	NCR: Yes No DQA:	Date:	
Resolution:	Dis	sposition:	QA: N/C Closed:	Date:	.

NCR:			WORK ORD	ER NON-CONFORMANC	E (NCR)			
D.4.T.F		Description of NC	Description of NC Corrective Action Section B					
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Approval Chief Eng	Approval QC Inspector
				,				

Picklist Print

Friday, April 16, 2010 12:57:33 PM

Work Order ID: 57838

Parent Item:

D3911-7

Parent Item Name:

Component Item ID/

Basket Plate-Eyebolt Receiver

Comments:

Item Name

IPP REV:A NEW ISSUE JLM 10-02-09 VERIFIED BY:EC

REV:B AS PER REV B 10-03-23 JLM VERIFIED BY:DD

Replacement Mfg/ Item ID

Purch Purchased

Primary Bin Item Location No

Last Location

Route Seq ID 100

IPP

Unit of Measure sf

Qty on Hand 20.2000

Remaining Qty Qty To Pick Issued 0.8059 1.1

Start Date: 4/19/2010

Start Qty: 24.00

Date Issued

Required Date: 4/23/2010

Required Qty: 24.00

Status

Page 1

M304S11GA

304/316 0.125 Sheet

•

Warehouse

Loc Qty Loc Code Location Main Warehouse MAT19 20.2 112663

EDUCIL

Dart Aerospace Ltd

W/O:			WC	RK ORDER CHANG	ES					
DATE	STEP	PRO	CEDURE CHA					Qty Approval Chief Eng / Prod Mgr QC Inspec		
					-					
		·								
Part No		PAR #:							Date:	
	R	esolution:							Date: _	
NCR:		\	WORK ORDI	ER NON-CONFORMA	NCE	(NCR)				
DATE	STEP	Description of NC Section A	Initial	Corrective Action Section Action Description	on B	Sign &	Verifica		Approval	Approval
		Section A	Chief Eng	Chief Eng		Date	Section	C	Chief Eng	QC Inspector
		:								
				· · · · · · · · · · · · · · · · · · ·						
·										

DART AEROSPACE LTD	Work Order:	27838
Description: RACKET PINTE-EYEROIT RECEIVED	Part Number:	D3911-7
Inspection Dwg: D3911-7 , Rev: C		Page 1 of 1


FIRST ARTICLE INSPECTION CHECKLIST

X First Article X Prototype

Drawing Dimension	Tolerance	Actual Dimension	Accept	Rejest	Method of Inspection	Comments
Ø .257	4 006 cc1	,760	8			
6 ,129	+,005-001	(139	Xo			
,375	th 010	.375	>			
1,000	rL 010	1.001	8			
,454	th ow	,457	8			
1,99	4 .030	1.99	>			
, 83	4 .030	.833	2			
1.75	4 .030	1.747	と			
1.000	7- 010	1,002	4			
,450	1/ .010	.448	%			
,500	th .010	.497	*			
.150	61- · 010	,150	*	ļ		
.756	t/ow	.248	8			
,500	J00	_ SO 1	A			
1,100	t/ao	1.100	ه ا			·
1.250	4010	1.753	6			
1.763	4-010	1,764	Y			
ગ્રગ	4- 030	3.266	8			,
1125	71010	811,	\$			
					,	

Measured by:	Audited by:	Prototype Approval:	
Date: 10-4-19	Date: 10/04/20	Date:	

Γ	Rev	Date	Change	Revised by	Approved
L	VEA	Date	0	KJ/JLM	1 1
	Α		New Issue	NJ/JLIVI	L



Dart .	Aeros	pace	Ltd
--------	--------------	------	-----

W/O:		WORK ORDER CHANGES											
DATE	STEP	PRO	PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
Part No: PAR #: Resolution:		PAR #:	Fault Category:			ICR: Yes No DQA:			Date:				
			Disposition: Q			4: N/C Closed:			Date:				
NCR:		V	VORK OR	DER NON-CONFORM	IANCE	(NCR)							
DATE STE	STEP	Description of NC Section A	Corrective Action Section B Initial Action Description			Sign &	Verificati			Approval			
			Chief Eng	Action Description Chief Eng		Date	Section C	Chief Eng	QC Inspector				
										-			
		•											
								,					